Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: SUSAN 3-25-1

Field Name: GOOSENECK Well File #: 11381

Date Incident: 4/4/2014 Time Incident: 11:00 Facility ID Number:

County: DIVIDE Twp: 163 Rng: 101 Sec: 25 Qtr: C SE

Location Description:

Submitted By: Adam Rookey Received By:

Contact Person: Curt Jensen

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Cultivated Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.6 MileDistance Nearest Water Well:0.6 Mile

Type of Incident: Fire

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.1	Barrels			0.1	barrels
Brine	0.1	Barrels			0	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/6/2015 Clean Up Concluded: 4/11/2014

Risk Evaluation:To be determined

Areal Extent:

estimated 50'x15' area W/NW of topsoil potentially impacted by mist from fire

Potential Environmental Impacts:

potential topsoil of area immediately west of treater; to be determined

Action Taken or Planned:

small isolated fire at the treater. Ensuring fire is completely out for safe working environment. Personnel being mobilized for clean up and RCA of fire.

Wastes Disposal Location: at an appropriate and approved disposal facility

Agencies Involved: John Axtman of the NDIC

Updates

Date: 4/4/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted a large area off of location. Followup is necessary.

Date: 4/9/2014 Status: Inspection Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

4/9/14 - 13:30 on location. Minor, scattered oil blobs remain within the lease boundaries in the NW corner of the location. Adjacent area outside that area has been tilled from appearances. Only very minimal oil spots on some wheat stubble was visible. NDIC has been informed verbally of the inspection results and will take oversight of the on-location residual cleanup. No further inspections needed in this incident.